

From glowbugs@theporch.com Mon Aug 12 19:21:03 1996
Return-Path: <glowbugs@theporch.com>
Received: from uro (localhost.theporch.com [127.0.0.1]) by uro.theporch.com
(8.8.Alpha.7/AUX-3.1.1) with SMTP id TAA21835; Mon, 12 Aug 1996 19:13:16 -0500
(CDT)
Date: Mon, 12 Aug 1996 19:13:16 -0500 (CDT)
Message-Id: <199608130013.TAA21835@uro.theporch.com>
Errors-To: ws4s@midtenn.net
Reply-To: glowbugs@theporch.com
Originator: glowbugs@theporch.com
Sender: glowbugs@theporch.com
Precedence: bulk
From: glowbugs@theporch.com
To: Multiple recipients of list <glowbugs@theporch.com>
Subject: GLOWBUGS digest 259
X-Listprocessor-Version: 6.0c -- ListProcessor by Anastasios Kotsikonas
X-Comment: Please send list server requests to listproc@theporch.com
Status: 0

GLOWBUGS Digest 259

Topics covered in this issue include:

- 1) Misc VHFfor trade
by wj5j@juno.com (John D Hensley)

Date: Mon, 12 Aug 1996 18:56:03 PST
From: wj5j@juno.com (John D Hensley)
To: Boatanchors@theporch.com
Cc: Glowbugs@theporch.com
Subject: Misc VHFfor trade
Message-ID: <19960812.190512.5159.3.wj5j@juno.com>

Hello group,

The following items are available for you
upper-band enthusiasts preferring pocket
sized wavelengths:

BC-625A Bendix transmitter. Looks complete,
no covers, and was probably modified for local
power; dusty w/spider webs (!).

Nice homebrew VHF transmitter probably from
QST or handbook article. Socketed for FT243
spacing xtal; utilizes the 832A pa tube. Has

4 pin femail Jones connector onboard for pwr
hook up. No supply yet. Dusty, nice little unit.

8298 power beam tube with socket

4CX250R (7580W) Eimac ceramic (PMI pull;
should be okay)

7823 ceramic pa tube (RIT, no way to test)

Type 15E tube (one JAN, one Eimac)

Motorola FM Station frequency deviation monitor
Model T1130A. Built in WWV receiver, complete,
no manual; rack mount style.

Motorola handset element, part no. 59-852603. NIB

Bendix filter (unknown use). Believe replacement part
for UHF gear. Bendix stk number 6139-10-58820-1
and case stamped 10-58820 and 1165168. Unit is
4" long, 3" diameter. Uses bendix 45-2 4 pin fittings
in and out (m/f) and has 2 pin female on side probably
for pwr. Flange mount, 4 bolt pattern 2 3/8" spacing.
NOS.

Trade any or all for HF or RTTY what-have-you ; looking
for 540 & 560 Tek plug-ins, 560 series cart, 7pin/9pin
receiving tubes, etc. etc.

73, Doug WJ5J

***** WJ5J/NNN0BXX *****
WTB: National AN/WRR-2A or FRR-19 or R274x (SX-73)
WTF: Nat'l rack spkr, frame, xcal/nbfm module; KS1 p.s.
Needed: SR150 inner adjusting knob, SX-100 band knob,
spare key buttons for model 19 tty; tty repair tools/parts
Also need 51J4/R388A parts unit or will buy repairable unit.
***** wj5j @ juno.com *****

End of GLOWBUGS Digest 259
